



Atlas Pixal
Multi Purpose
Assembly
Fixture

Base for Chip gluing and wire bonding



Base for testing, burn in and rework



Read out electronics support
frame


Adapter card support

Hybrid aligns to these edges



Base to align chip with chip vacuum chuck

Vacuum cups



Vacuum connection



Place Hybrid and align, hold with vacuum



Install mechanical clamps




Thumb screws for hold down
(captured screw)

Glue mask carrier

Alignment pins

Glue mask



Glue mask assembly

